


RA7000 12 Core ITT Canon 1.0/2.3 Connector Cable Assembly
118-101



PARTS LIST

ITEM No	FCA	DESCRIPTION	QTY
1		CABLE COAXIAL RA7000 12 CORE.	A/R
2		CONNECTOR 1.0/2.3 CRIMP PLUG.	12
3		SLEEVE HEATSHRINK. $\varnothing 22 \times 60.0 \text{mm}$.	1

